






				Ca	visley International GmbH	
Dat	a tra	nsfei	r to autom	ated anal	ytics	
gener	enerating data for data transfer					
rack no.	column	row	sample no.	comment		
2008-06-	18 11:09:12	2			time stamp	
123456	1	A	8000400010001387	good read	code deciphered	
123456	2	А	8000400010001367	good read		
123456	3	A	8000400010001375	good read		
123456	4	A	8000400010001378	good read		
123456	5	A	8000400010001413	good read		
123456	6	A	8000400010001438	good read		
123456	7	A	8000400010001420	good read		
123456	8	A	0	code error	code not recognize	
123456	9	A	8000400010001439	good read		
123456	10	A	8000400010001417	manually corrected	corrected data ent	
123456	11	A	8000400010001418	good read		
123456	12	A	0	vacant	vacant position	
123456	1	в	8000400010001293	good read		
123456	2	в	8000400010001352	good read		
w.caisle					14	





















process	duration	throughput	comment
positioning on 96-rack	+/- 3 min	2000 samples/h	possible identification of damaged sample tubes
registration with scanner	+/- 3 min	2000 samples/h	possible cleaning of dirty sample tubes
opening with punching tool	+/- 2 min	3000 samples/h	punching tool needs to be decontaminated on a regular basis

